

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

5/021/113

Michael O. Leavitt Governor Kathleen Clarke **Executive Director**

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

July 25, 2001

This inspection for "Black Rock" was inadvertently filed under the wrong file #. new # Created for Black Rock - 5/027/103.

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Specialist 1

BLACK ROCK

RE:

Site Inspection, Mert Hamilton, Rich Gulch Project, S/027/088, Millard County, Utah

Date of Inspection:

June 19, 2001

Time of Inspection:

3:00 - 3:30 p.m.

Conditions:

Ouite hot

Participants:

Tom Munson, DOGM

Purpose of Inspection: To inspect the site while in the area

I stopped at this limestone operation located north of Milford. I walked around the site, but I did not GPS the site because the BLM has already recently GPS'd the site at a little over three acres.

Photos were taken of the site. There are two crushers, a couple of conveyors and a hopper at the site. They are blasting black limestone to reduce it down to about a 10 mesh size so they can sell it to the asphalt industry and possibly for cement products too. They expect to be up and running in a week to ten days. Mark Layton will be in charge of the project. He thought they should be a little further along than they were, but they are moving ahead.

Mert Hamilton, Operator

Mert Hamilton-ins.doc

H:\temporary holding folder\

H:\temporary holding folder\

BLACK ROCK

ALL THESE

PICTURE ARE

OF BLACK ROCK



P0002302.JPG 06/20/1901



P0002303.JPG 06/20/1901



P0002304.JPG 06/20/1901

ALL CROSS OUTS ARE WRONG!



P0002305.JPG 06/20/1901



P0002306.JPG 06/20/1901



P0002307.JPG 06/20/1901



P0002308.JPG 06/20/1901



P0002309.JPG 06/20/1901



P0002310.JPG 06/20/1901



P0002311.JPG 06/20/1901



P0002312.JPG 06/20/1901



P0002313.JPG 06/20/1901



P0002314.JPG 06/20/1901